Real Time Measurement of Position as well as Direction using Linear Variable Differential Transformer

Ch.V.Suresh^{*}, G.Ramu^{**}

Abstract—

Linear Variable Differential Transformer (LVDT) is a transducer which converts mechanical displacement into output electrical corresponding to the input displacement. This paper describes the procedure of measuring displacement and the direction of the movable iron of LVDT. Normally this is impossible with conventional LVDT operation. The construction and working of the modified LVDT was explained. The results of the conventional LVDT and the modified LVDT were compared. The procedure to measure exact position and displacement direction of movable iron was given.

The magnetic field distributions of modified LVDT connections were analyzed using FEMM (Finite Element Method Magnetics) software. The analysis results were given and the corresponding density plots were plotted.

Index Terms — DC Conversion Circuit, Direction Measurement, LVDT, Position Measurement.

I. INTRODUCTION

LVDT is most widely used inductive transducer for translating the linear motion into electrical signal. Magnetic coupling between primary and secondary coils is established by using a soft and movable iron core. In normal LVDT both the secondary coils are connected in series opposition. However, the output voltage is zero. As the core moves up or down, the induced voltage in one secondary coil increases while that of the other decreases. Here the magnitude of the output voltage is in AC nature. In this case measuring both position as well as direction of movable iron is difficult.

Normally LVDT has one primary winding (P) and two identical secondary windings (S1, S2) wounded over a hollow pipe of non-magnetic and insulating material and consists equal number of turns placed on each of the secondary windings. A soft iron is placed inside of the pipe. The direction of movement of the iron makes output voltage increases or decreases. If the soft iron moves in forward direction the output voltage is in phase. If the soft iron moves in backward direction the corresponding output voltage with 180 Deg out of phase [1]. In this case it is very difficult to

Manuscript submitted on March 27th, 2012. This work was supported in part by the Department of Electrical and Electronics Engineering (EEE), Chaitanya Institute of Science & Technology (CIST), Kakinada, Andhra Pradesh, India.

* - Corresponding author for this paper. Assistant Professor-EEE, CIST.

estimate the exact position and direction of movement.

It is clear that LVDT has limited range of displacement and range varies from ± 0.01 mm to ± 0.25 mm.

II. REVIEW OF THE RELATED WORK

Linear Variable Differential Transformers (LVDTs) are devices for the measurement of distances. They are used to measure tiny to large ranges, from millionths of an inch to many inches. Thus, LVDTs not only sensitive and accurate in detecting mechanical motion, it is also sensitive to the direction of the motion. Since LVDTs are transformers and there is no electrical continuity between primary and secondary coils.

DLD series LVDT Demodulators [2] are developed for measuring position and direction of the movement. But it needs following equipment

- 1. Setting SPAN switches.
- 2. Setting SPAN potentiometers.
- 3. Offset the demodulator.
- 4. Determining electrical null.
- 5. Locate mechanical null and superimpose it with the electrical null.

This procedure is very difficult and time consuming. It requires skilled labour.

Linear Technology Corporation (LTC) developed a new LVDT signal conditioning which combines LTC1967 RMS to DC Converter with a separate phase detector circuit [3]. But it needs the following equipment.

- 1. OP-Amp circuits.
- 2. Phase lag compensators.
- 3. Phase modulators and comparators.
- 4. Bias setter.
- 5. Amplitude modulator.

Finally the output of this conditioner gives the information about the displacement (Amplitude) and direction (Phase) of the movable transformer core.

Hareem Tariq [4], have been developed low frequency damping sensors for seismic attenuation systems for gravitational wave interferometers and for mirror positioning. One type of these linear variable differential transformers has been designed to be most insensitive to displacement allowing 3D movement of the sensor to read precise position along the sensitivity. A second LVDT geometry has been designed to measure displacement of the vertical positions. But this

^{** -} Head of the Department, EEE, CIST, Kakinada.

Ch.V.Suresh, G.Ramu / International Journal of Engineering Research and Applications (IJERA)

ISSN: 2248-9622

www.ijera.com

Vol. 2, Issue 3, May-Jun 2012, pp. 246-252

system makes use of electronics and leads to the saturation problems.

All the above reviews lead to the modified form of the conventional LVDT to measure displacement and direction very precisely.

III. METHODOLOGY

A. Conventional and Modified LVDT connections

The conventional LVDT is shown in Fig. 1, it consists one primary coil excited by AC supply, two secondary coils and movable iron core.

By connecting AC voltmeter across the output terminal of the LVDT, an RMS voltage proportional to the displacement will be displayed (that do not have polarity), not direction.



Fig.1. Conventional LVDT with back to back connection of secondary windings.

Both direction and displacement can be measured by using rectified output with the modified design as shown in Fig. 2.



Fig.2. Modified LVDT with series connection of secondary windings.

B. Design of Modified LVDT

Design constraints are mainly to limit construction effort and use easily available materials. The number of turns in primary is 100 and each of the secondary consists 200 turns with double layer winding. 1/2" PVC pipe was used to wound the coils and a section of 7/16" iron rod for core. Here 0.315 mm (30 SWG) insulated copper wire was used to wound the coils.

1. Design Specifications

- ID of the PVC pipe = 1.66 cm
- OD of the PVC pipe = 1.7 cm
- Resistance of 30SWG wire = 0.2212 Ohm/mm
- Diameter of copper wire = 0.315 mm
- Diameter of the core = 1.5 cm
- Material of the core = iron



Fig.3. Modified LVDT connections with dimentions.

C. Working Specifications

- 1. LVDT Excitation (i/p) : 1-phase, A.C, 50Hz, 6V, 1A
- 2. Output Voltage Range :+2.61 to -4.62
- 3. Zero Adjustment Range : ± 0.3 V
- 4. Linearity $\pm 0.05\%$ of full scale
- 5. Operating Temperature : 20 to 140 deg F
- 6. Power Consumption : 0.2212 watts

D. Working of the Modified LVDT

The position is indicated by the amplitude of DC voltage. The direction is indicated by polarity of DC voltage, how the positive and negative voltages are increasing and decreasing.

The block diagram shown in Fig. 4 describes the operation of modified LVDT.





1-phase, 230V, 50Hz, AC supply was given to the primary winding. Initially movable iron was placed at center position. The upper secondary winding terminals were named as 11 and 12. Similarly lower secondary winding terminals were named as 21 and 22. In modified LVDT, the 12 and 21 terminals were short circuited and the output was taken at 11 and 22 terminals. Here the short circuit is considered as neutral terminal (N) for step transformers and the upper terminal '11' is considered as phase for transformer '1' and terminal '22' was considered as phase terminal for transformer '2'.

The above connections can be observed from the Fig. 5.

Ch.V.Suresh, G.Ramu / International Journal of Engineering Research and Applications (IJERA) ISSN: 2248-9622 www.ijera.com





Fig.5. Modified LVDT working connections

The output terminals of upper transformer are connected to Diode Bridge to convert AC voltage to DC voltage, and this positive voltage can be measured by using normal multimeter. Similarly the same set-up was arranged for lower transformer. And the polarity of the voltage is negative. Hence the total voltage of these two voltmeters gives the voltage corresponds to the displacement of the movable iron.

1. Case 'A':

If the iron is placed in the forward direction, then, the voltage in the voltmeter 'V1' is high and the voltage in the voltmeter 'V2' is very low with negative sign. The sum is positive voltage.

2. Case 'B':

If the iron is placed in the backward direction, then, the voltage in the voltmeter 'V1' is low and the voltmeter 'V2' reading is high, and results negative voltage.

3. Case 'C':

If the iron is placed at the center position across the primary winding, then the reading of voltmeters 'V1' and 'V2' gets cancelled each other and resultant voltage is 'zero'. This point is known as null position.

E. FEMM Analysis

Before going into the practical implementation of the modified LVDT operation, it is necessary to analyze the magnetic flux density distribution and the field intensity distributions across LVDT primary and secondary coils.

FEMM [5] is simulation software to design and analyse the flux and field intensity distributions for a low frequency electromagnetic problems on two dimensional planar and axisymmetric domains. The problem currently addresses linear magneto static problems.

Magneto static problems are problems in which the fields are time-invariant. In this case, the field intensity (H) and flux density (B) must obey

$$\nabla \times \mathbf{H} = \mathbf{J} - (1)$$

 $\nabla \cdot \mathbf{B} = 0 - (2)$

Subjected to a constitutive relationship between B and H for each material

$$\mathbf{B} = \boldsymbol{\mu} \mathbf{H} \quad \textbf{--(3)}$$

FEMM solves the above equations and shows the flux density and field intensity distributions. The following graphs were obtained for the modified LVDT with the following parameters.

FEMM problem parameters:

1. The entire problem is defined in 'cm'.

- 2. Four blocks were considered for analysis of the magnetic field.
 - Air
 - Secondary Winding 1
 - Primary Winding
 - Secondary Winding 2
- 3. Secondary coils (1,2) with 200 turns.
- 4. Made up of Standard Wire Gauge (SWG) copper material.
- 5. Diameter of copper wire is 0.315mm (30swg).
- 6. Current flowing is 0A.
- 7. Primary winding coil with 100 turns.
- 8. Made up of Standard Wire Gauge (SWG) copper material.
- 9. Diameter of copper wire is 0.315mm (30swg).
- 10.Primary coil current is 1A.
- 11.Mesh size is 0.1.

12. 'Prescribed A' boundary conditions with zero quotients.







Fig.7. Distribution of flux density (B)



Fig.8. Distribution of normal flux density (B.n)



Ch.V.Suresh, G.Ramu / International Journal of Engineering Research and Applications (IJERA) ISSN: 2248-9622 www.ijera.com

Vol. 2, Issue 3, May-Jun 2012, pp. 246-252

Integral results on the LVDT coils surface

- Normal flux = 1.49822e-012 Webers
- Average B.n = 1.37451e-009 Tesla
- MMF drop along contour = -87.6404 Amp-turns
- Average H.t = -804.04 Amp/Meter
- Contour length = 0.109 meters
- Surface Area = 0.00109 meter^2
- Force in x-direction = -0.000142559 N
- Force in y-direction = 1.31232e-006 N
- Torque about (0,0) = 1.06174e-005 N*m
- Result = 2.21269e-007 Webers^2
- Average $(B.n)^2 = 2.02999e-006$ Tesla²

F. Practical Implementation

The step by step implementation of the modified LVDT is given below.

- 1. Design normal LVDT with 100 turns in primary and a total 200 turns in each secondary winding with double layer.
- 2. Give AC supply with 1Amp current to primary winding.
- 3. Place the iron core across the primary coil in such a way that the voltage induced in the both the secondary's gets cancelled each other and this position is known as 'Null Position'.
- 4. Now move the iron in forward direction and note the readings of both voltmeters.
- 5. Similarly repeat the Step 4 in reverse direction.
- 6. Plot the graph by taking forward displacement along positive X-axis and reverse displacement along negative X-axis and total voltage along Y-axis.
- 7. Determine the linearity i.e. lower bound point and upper bound point.
- 8. Now calculate the slope (m) of the linearity and determine the line equation passing through origin having the slope (m) [i.e. y=mx].
- 9. Now move the iron to any arbitrary position and note the readings of both the voltmeters and the total voltage. Now the following inferences were obtained
 - If the sign of the total voltage is positive indicates forward direction and the value indicates the position (x) of the iron. [i.e. x=y/m]
 - If the sign of the total voltage is negative indicates reverse direction and the value indicates the position (x) of the iron. [i.e. x=y/m]
 - If the value of the total voltage is zero indicates 'Null Position'.
- 10. The results were validated using graph and with the known values.
- 11. To increase the accuracy and the reliability of the calculations, a 'C' language program was developed.

The practical view of the developed LVDT is shown in Fig.17.



Fig.17. Real time working model of Modified LVDT

G. Conventional LVDT & Modified LVDT Results

The normal LVDT output voltages in both the forward and reverse directions.

 Table.1: Voltages in forward/backward directions in

	1101		Л		
S.No	Forward Distance	v	Reverse Distance	v	
1	1	0	0	0	
2	2	0.2	0.4	0.2	
3	3	0.4	0.8	0.4	
4	4	0.6	1.2	0.6	
5	5	0.8	1.6	0.8	
6	6	1	2	1	
7	7	1.2	2.4	1.2	
8	8	1.4	2.8	1.4	
9	9	1.6	3.2	1.6	
10	10	1.8	3.5	1.8	
11	11	2	3.7	2	
12	12	2.2	3.8	2.2	
13	13	2.4	3.8	2.4	
14	14	2.6	3.6	2.6	
15	15	2.8	3.4	2.8	

The graphical representation of the above values shown in Fig.18, there is a linear relationship between the displacement and the voltage induced in the secondary windings.



Fig.18. Variation of voltages in Conventional LVDT The Modified LVDT output voltages with respect to distance and directions are listed in Table.2.

 Table.2: Voltages in forward/backward direction for Modified LVDT

Forward Direction					Reverse Direction			
5.100	Х	V1	V_2	V _{Total}	Х	V_1	V_2	V _{Total}
1	0	2.97	-2.97	0	0	2.97	-2.97	0
2	0.2	3.15	-2.65	0.5	-0.2	2.67	-3.17	-0.5

Ch.V.Suresh, G.Ramu / International Journal of Engineering Research and Applications (IJERA) www.iiera.com ISSN: 2248-9622 Vol 2

					V	'ol. 2, 1	lssue 3,	May-J	un 2012, pp. 246-252
3	0.4	3.32	-2.32	1.0	-0.4	2.40	-3.4	-1	While in step 2
4	0.6	3.48	-1.98	1.5	-0.6	2.11	-3.61	-1.5	(V1 V2) correspo
5	0.8	3.64	-1.64	2	-0.8	1.85	-3.85	-2	
6	1	3.70	-1.3	2.4	-1	1.60	-4.10	-2.5	gives the position
7	1.2	3.83	-1.08	2.75	-1.2	1.32	-4.32	-3	Fig. 21 shows the
8	1.4	3.85	-0.85	3	-1.4	1.04	-4.55	-3.51	Table.3.
9	1.6	3.79	-0.54	3.25	-1.6	0.83	-4.64	-3.81	The flow chart
10	1.8	3.72	-0.37	3.35	-1.8	0.65	-4.77	-4.12	The now chart
11	2	3.68	-0.27	3.41	-2	0.48	-4.78	-4.30	program was given
12	2.2	3.50	-0.25	3.25	-2.2	0.33	-4.79	-4.46	
13	2.4	3.32	-0.20	3.12	-2.4	0.22	-4.72	-4.5	
14	2.6	3.09	-0.09	2.96	-2.6	0.16	-4.62	-4.46	Initializ
15	2.8	2.78	-0.07	2.71	-2.8	0.11	-4.48	-4.37	
16	3	2.51	-0.05	2.46	-3	0.08	-4.31	-4.23	Read lower
								-	

The graphical representation of the above values shown in Fig. 19, there is a linear relationship between the displacement and the voltage induced in the secondary windings.



Fig.19. Variation of voltages in Modified LVDT.

Graphs 1 and 2 are very similar and there exists a relation between displacement and the voltage. Direction is given by the sign of the total voltage.

The linearity exists between lower bound point (-1.6,-3.81) and upper bound point (1,2.4) with a tolerance of 0 to \pm 0.25mm.

H. Validations

The following table gives the details of validation of the modified LVDT using graph and known values.

Table.3: Validation table for Modified LVDT output

			voltages		
S.No	V ₁	V ₂	V _{Total}	Direction	Displacement*
1	3.27	-2.3	0.97	Forward	0.35
2	3.37	-1.96	1.41	Forward	0.5
3	3.81	-0.7	3.11	Forward	1.52
4	1.48	-4.18	-2.7	Backward	-1.1
5	0.22	-4.73	-4.51	Backward	-2.43
6	0.16	-4.56	-4.40	Backward	-2.8
7	3.5	-0.12	3.38	Forward	2
8	1.71	-3.96	-2.25	Backward	-0.9

*Displacement is with respect to the last position of the iron.

I. Software Implementation

A C-language program was developed to calculate displacement and position of the iron very accurately with speed. The steps to develop C program were given below.

- 1. Calibration of the program.
- 2. Calculation of the displacement and position.

In calibration procedure C-program was programmed by using lower and upper bound points and null value voltages.

While in step 2, if you enter the values of the voltmeters (V1, V2) corresponding to displacement, then the program gives the position and displace of the iron from null position. Fig. 21 shows the output screen of the possible cases given in Table.3.

The flow chart representation of algorithm used for the program was given below.



Fig.20. Flow chart for C-praogram implementation **

****** WELCOME TO LVDT PROJECT ******						
Step 1: Calibration of program						
Enter the values for lower bound 'X1,Y1'						
-1.6 -3.81						
Enter the values for upper bound 'X2,Y2'						
1 2.4						
SLOPE Value is : 2.388462						
Enter null v10&v20 values:						
2.97 -2.97						
Step 2: Calculation of POSITION & DIRECTION						
Enter values for V1 and V2						
3.37 -1.96						
DIRECTION IS : Forward						
DISPLACED DISTANCE FROM LAST POSITION						
0.590338						
Step 2: Calculation of POSITION & DIRECTION						
Enter values for V1 and V2						
0.22 -4.73						
DIRECTION IS : Backward						
DISPLACED DISTANCE FROM LAST POSITION :						
2.478583						

Ch.V.Suresh, G.Ramu / International Journal of Engineering Research and Applications (IJERA) ISSN: 2248-9622 www.ijera.com

Vol. 2, Issue 3, May-Jun 2012, pp. 246-252

Step 2: Calculation of POSITION & DIRECTION							
Enter values for V1 and V2							
3.5 -0.12							
DIRECTION IS	: Forward						
DISPLACED DISTANCE F	ROM LAST POSITION :						
3.303382							
Step 2: Calculation of POSITION & DIRECTION							
Enter values for V1 and V2	2						
1.71 -3.96							
DIRECTION IS	: Backward						
DISPLACED DISTANCE F	ROM LAST POSITION :						
2.357166							
Step 2: Calculation of POSITION & DIRECTION							

Enter values for V1 and V2 **Fig.21**. C-program output for the various input voltages

J. Limitations

- This project has the following limitations.
- 1. Magnetic saturation of coils was neglected.
- 2. The losses because of transformers decrease the reliability of the sensor.
- 3. The losses due to eddy currents and hysteresis were neglected.
- 4. The materials used in equipment are not magnetically calibrated.

IV. CONCLUSION

Hence, this article confirms that the measurement of position as well as direction of the movable iron of LVDT was possible if the connections of the secondary windings were modified. The FEMM results confirm that the magnetic field distribution from primary coil to secondary coil is uniform. So that the voltage induced in the secondary windings was according to the movement of the iron.

The output results of Modified LVDT displacements were valid and these results were verified using c-program.

REFERENCES

- 1. "How sensors work LVDT displacement transducer", http://www.sensorland.com/HowPage006.html (current December 2002).ACT
- 2. "DLD series LVDT Demodulators", Sensotec, Document Number:008-0532-00, December, 2005.
- 3. Cheng-Wei Pei, "Design Notes-362", Precision LVDT signal conditioning using Direct RMS to DC conversion, Linear Technology Corporation, 2005.
- 4. Hareem Tariq. Etal, "The linear variable differential transformer (LVDT) position sensor for gravitational wave interfereometer low-frequency controls", Volume-489, issue 1-3, August, 2002, Pages 57-576.
- 5. David Meeker, "FEMM 4.2 Magnetostatic Tutorial", January 25, 2006.
- 6. Beckwith, Buck & Maragoni, Mechanical Measurements, Third Edition, 1982.

- 7. James Daly, Willian Riley & Kennet McConnell, Instrumentation for Engineering Measurements, 2nd Edition, 1984, John Wiley & Sons.
- 8. Mishra, SK & Panda, G, A novel method for designing LVDT and its comparision with conventional design, Proceedings of the 2006 IEEE Sensors Application Synposium, pages: 129-134, 2006.
- 9. Shang-The Wu, Szu-Chieh Mo, Bo-Siou Wu, An LVDTbased self actuatuin displacement transducer, Science Direct, Sensors and Actuators A 141 (2008) 558-564.
- 10. RDP Electronics, "Linear Variable Differential Transformer Principle of Operation", <u>http://www.rdpe.com/displacement/lvdt/lvdt-</u> principles.htm, (current December, 2002)
- 11. Sinan Taifour, Etal., "Modelling & Design of a Linear Variable Differential Transformer" MS'08, Jordan

BIBLIOGRAPHY



Ch. V. Suresh working as an Assistant Professor in the Department of Electrical & Electronics Engineering, Chaitanya Institute of Science & Technology, Kakinada, Andhra Pradesh, India. His areas of interest are Electrical Machines, Nuclear Power Engineering,

Machines, Nuclear Power Engineering, Modeling and Simulation of Micro Electro-Mechanical Systems and Electrical Power Systems.

G.Ramu working as Professor & HOD in the Department of Electrical & Electronics Engineering, Chaitanya Institute of Science & Technology, Kakinada, Andhra Pradesh, India.

He has 15 years of teaching experience. His areas of interest are Electrical Machines, High Voltage Engineering, Electric traction, Electrical Measurments & Network Analysis.