RESEARCH ARTICLE OPEN ACCESS

# **Welding Techniques**

# Ahmad Hussain Albloushi, Abdulhadi Hussain Albloushi

Public authority for applied education and training. Kuwait Ministry of education. Master's degree. Kuwait Corresponding Author: Ahmad Hussain Albloushi

**ABSTRACT:** For decades and centuries welding is considered one of the most used process in many industries, it used to join metals by exposing them to extreme heat to create welding form. There are several type and form for welding, and it can be utilized like electrical, gas and laser beam welding. also, several welding methods were created and developed like: shielded arc welding, semi-automatic and automatic methods like electron slag welding and gas metal arc welding, beam of electron welding and laser beam welding, and now in the modern era, robot welding becomes the most welding used in factories. until this day, welding methods continue to grow and develop, and got great attention of understanding for welding properties and quality. although welding has many benefits. Welding is considered dangerous and hazardous. And precautions are highly recommended to avoid burns, poison gas fumes and ultra violet waves.

**Key-words:** - welding; materials: techniques

Date of Submission: 15-12-2019

Date Of Acceptance: 27-12-2019

## I. INTRODUCTION:


Welding can be defined as a combination of materials, mostly metals and thermo plastics. this metal fusion process is done after exposing the metal to high heat, in addition to filler materials to make a molten metal pool. Which it cools after to form the recommended joint or welding form. Also, pressure can be used with heat in some occasions to make the weld.

Many forms of energy can be utilized in welding, such as gas flames, electrical arc, laser beam and ultra sound. Typically welding process can be achieved in several circumstances, like in the air welding, welding underwater and welding in outer space. In the meantime, although welding has many benefits. Welding is considered dangerous and hazardous. And precautions are highly recommended to avoid burns, poison gas fumes and ultra violet waves.

By the beginning of the 20<sup>th</sup> century, forge welding was the only type that was used by blacksmiths. For decades and centuries forge welding was used to join metals by exposing them to extreme heat and pounding after that. Soon after that, oxy fuel welding, arc welding and resistance welding was developed late that century. Early 20th welding technology significantly during world war 1 and world war 2. As consequence of the war, it was demanded to develop inexpensive and reliable joining methods. After the war, the welding industry developed furthermore, and several welding methods were created and developed like: shielded arc welding, semi-automatic and automatic methods likeelectron slag welding and gas metal arc welding. The

industry continuous to grow in the latter half of 20<sup>th</sup> century, producing a beam of electron welding and laser beam welding, and now in modern era, robot welding becomes the most welding used in factories. And until this day, welding methods continue to grow and develop, and gotgreat attention of understanding for welding properties and quality.

\_\_\_\_\_



Cross-section of welded joint

#### Arc welding:

This process is used to maintain and keep an electric arc between abase material with the electrode. by using a welding power supply, to make welding point melt. it can be direct or alternating current, non-consumable orconsumable electrodes. Sometimes, filler materials are used as well.



Submerged arc welding

# Power supplies:

There are many different power supplies can be used to provide the necessary energy for arc welding processes. But the most common type used is constant current and voltage supplies. Because, the current related to the amount of heat input, and the voltage, in the other hand is related to the length of the arc. They relatively maintain constant even in high demanding situations.



Frame weld joint

#### **Processes:**

#### 1- Shielded metal arc welding (S.M.A.W):

the most arc welding types used is manual metal arc welding and stick welding, it used an electric current to produce an arc between the electrode and the base material. This consumable material is made from steel. It protects and cover the welding surface from contamination and oxidation by producing co2 through welding process.

#### 2- Gas metal arc welding (G.M.A.W):

Ormig welding. Its an automatic or semiautomatic procedure, which uses a continuous wire food as an electrode and asemi-inert or inert gas mixture to provide protection from contamination. Like shielded metal arc welding, welding proficiency can be achieved with continuous training. But the speed of welding for gas metal arc welding is greater than shielded metal arc welding.

#### 3- Flux cored arc welding (F.C.A.W):

utilizes almost identical equipment, and uses wire consisting of a steel channel surrounding the fill material powder. This cored

wire consideredhigh value than the regular wire and may produce vapor or potentially filth.also,itconsidered one of the fastest welding speed methods.

## 4- Gas tungstenarc welding (G.T.A.W):

It's a manual welding procedure, which utilize a none consumable tungsten electrode, a semi-inert or inert mixture of gas, with a different filler material. Tungsten welding is good for welding thin materials, this type of welding is known for its high-quality welds by using a very stable arc. To achieve that, it requires a very excellent skills by the operator, and its only accomplished at low speed.G.T.A.W is good for weldinga wide range of metals, mostly onlightmetalsand stainless steel. it's typically used when top notch welds are needed, like motorcycles, automotive and aviationindustries.... etc.

## 5- Plasma bend affixing:

conjointly utilizes a metallic component transmitter anyway utilizes plasma gas to shape the circular segment. The bend is extra focused than the GTAW circular segment, making cross administration extra fundamental and thusly commonly constraining the strategy to an automated technique. attributable to its steady current, the methodology might be utilized on a more extensive change of texture thicknesses than will the GTAW technique, and what is more, it's a ton of snappier. It might be connected to all or any of a comparative-materials as GTAW aside from nuclear number (12) and programmed securing of chrome steel is one essential utilization of the strategy. A variety of the technique is plasma cutting, Partner in Nursing practical steel cutting strategy.

# 6- Submerged circular segment affixing:

might be a high-efficiency securing system inside which the curve is influenced underneath a covering layer of transition. This will build bend quality, since contaminants inside the environment region unit hindered by the motion. The rubbish that structures on the weld regularly falls off without anyone else's input and joined with the usage of an everlasting wire feed, the weld affidavit rate is high. working conditions territory unit, a ton of improved over various curve attaching forms, since the motion conceals the circular segment and about no smoke is made. the strategy is frequently utilized in exchange, especially for mammoth item and inside the production of welded weight vessels.

- 1- Atomic element fastening.
- 2- Carbon arc fastening.
- 3- Electroslag fastening.

- 4- Electro gas fastening.
- 5- Stud arc fastening.

#### Gas

The most widely recognized gas connection technique is oxyfuel connection, moreover called oxyacetylene connection. it's one in everything about most established and most flexible connection forms, anyway as of late it's subsided standard in modern applications.

It is still wide utilized for connection pipes and cylinders, in like manner as fix work. it's furthermore oft appropriate, and supported, for manufacturing a few styles of metal-based structure. Oxyfuel instrumentation is adaptable, advancing itself not exclusively to certain styles of iron or steel connection anyway moreover to brazing, braze-welding, metal warming (for bowing and shaping), and furthermore oxyfuel cutting.

The instrumentation is relatively shabby and simple, normally utilizing the burning of aliphatic compound in nuclear number 8 to give a connection fire temperature of with respect to 3100 °C. The fire, since it's less focused than an electrical circular segment, causes slower weld cooling, which may result in bigger remaining burdens and weld twisting, in spite of the fact that it facilitates the connection of high composite steels. an undifferentiated from technique, ordinarily alluded to as oxyfuel cutting, is utilized to hack metals.

Different gas connection ways, similar to air aliphatic compound connection, nuclear number 8 component connection, and weight gas connection square measure very comparative, normally contrasting exclusively inside the assortment of gases utilized. A water light is commonly utilized for precision connection of little things like adornments. Gas connection is furthermore utilized in plastic connection, despite the fact that the warmed substance is air, and furthermore the temperatures square measure rich lower.

# **Resistance:**

Opposition welding includes the age of warmth by going current through the obstruction brought about by the contact between at least two metal surfaces. Little pools of liquid metal are shaped at the weld territory as high current (1000–100,000 An) is gone through the metal. All in all, opposition welding strategies are effective and cause little contamination, however their applications are restricted, and the hardware cost can be high.

Spot welding is a well-known obstruction welding technique used to join covering metal sheets of up to 3 mm thick. Two terminals are all

the while used to cinch the metal sheets together and to go current through the sheets. The upsides of the strategy incorporate proficient vitality use, restricted work piece misshape Ning, high generation rates, simple robotization, and no required filler materials. Weld quality is altogether lower than with other welding techniques, making the procedure reasonable for just certain applications. It is utilized broadly in the car business—customary vehicles can have a few thousand spot welds made by mechanical robots. A specific procedure, called shot welding, can be utilized to spot weld tempered steel.

Like spot welding, crease welding depends on two anodes to apply weight and current to join metal sheets. Be that as it may, rather than pointed cathodes, wheel-formed terminals move along and regularly feed the work piece, making it conceivable to make long persistent welds. Before, this procedure was utilized in the production of refreshment jars, however at this point its uses are increasingly constrained. Other obstruction welding strategies incorporate glimmer welding, projection welding, and upset welding.


#### Energy beam

Vitality shaft connection ways, explicitly beam of light connection and electromagnetic radiation connection, are relatively new procedures that turned out to be very well-loved in high creation applications. the 2 forms are very comparative, varying most strikingly in their supply of intensity.

Laser pillar connection utilizes an incredibly focused on beam of light, while electromagnetic radiation connection is done partner degree exceedingly in a very} vacuum and uses an electromagnetic radiation. each have a truly elevated vitality thickness, making profound weld entrance potential and limiting the size of the weld space. every procedure are uncommonly snappy, and are basically programmed, making them incredibly gainful. the principal inconveniences are their horribly high instrumentation costs (however these are diminishing) and a weakness to warm splitting. Advancements during this space encapsulate laser-cross breed connection, that utilizations standards from each beam of light connection and circular segment connection for significantly higher weld properties.

## Geometry

Welds is geometrically prepared from numerous points of view that. The 5 essential sorts of weld joints ar the joint, lap joint, corner joint, edge joint, and T-joint. various varieties exist too for instance, twofold V arrangement joints ar portrayed by the 2 things of texture each decreasing to one focus reason at basic division their stature. Single-U and alphabetic character arrangement joints likewise are genuinely normal—rather than getting straight edges simply like the single-V and twofold V planning joints, they're sinusoidal, shaping the type of a U. Lap joints additionally are conventionally very 2 things thick—contingent upon the strategy utilized and furthermore the thickness of the texture, a few things is welded along in an exceptionally joint unadulterated science.



**Figure 1:** Common welding joint types – (1) Square butt joint, (2) Single-V preparation joint, (3) Lap joint, (4) T-joint.

Regularly, specific joint structures are utilized solely or only by certain welding forms. For instance, obstruction spot welding, laser pillar welding, and electron bar welding are most every now and again performed on lap joints. In any case, some welding strategies, as protected metal circular segment welding, are incredibly adaptable and can weld for all intents and purposes any kind of joint.

Moreover, a few procedures can be utilized to make multi pass welds, in which one weld is permitted to cool, and afterward another weld is performed over it. This takes into consideration the welding of thick segments orchestrated in a solitary V readiness joint.



**Figure 2**: The cross-section of a welded butt joint, with the darkest gray representing the weld or fusion zone, the medium gray the heat-affected zone, and the lightest gray the base material.

After assortment of connection, unmistakable locales will be known inside the weld space. The weld itself is named the combination zone—all the more explicitly, it's any place the filler metal was requested all through the connection strategy. The properties of the combination zone depend absolutely on the filler metal utilized, and its similarity with the base materials. it's circled by the warmth influenced zone, the domain that had its microstructure and properties adjusted by the weld. These properties depend on the base material's conduct once exposed to warm. The metal during this space is normally flimsier than each the base material and furthermore the combination zone and is also any place lingering stresses square measure found.

#### Quality

Frequently, the real measurement utilized for making a decision about the nature of a weld is its quality and the quality of the material around it. Numerous unmistakable variables impact this, including the welding technique, the sum and convergence of vitality input, the base material, the filler material, the motion material, the plan of the joint, and the collaborations between every one of these elements. To test the nature of a weld, either damaging or nondestructive testing techniques are ordinarily used to confirm that welds are without deformity, have adequate dimensions of remaining anxieties and twisting, and have worthy warmth influenced zone (HAZ) properties. Welding codes and particulars exist to control welders in appropriate welding method and in how to pass judgment on the nature of welds.

Warmth influenced zone the impacts of welding on the material encompassing the weld can be unfavorable—contingent upon the materials utilized and the warmth contribution of the welding procedure utilized, the HAZ can be of changing size and quality. The warm diffusivity of the base material assumes an enormous job-if the diffusivity is high, the material cooling rate is high and the HAZ is moderately little. Then again, a low diffusivity prompts slower cooling and a bigger HAZ. The measure of warmth infused by the welding procedure assumes a significant job also, as procedures like oxyacetylene welding have an unconcentrated warmth info and increment the span of the HAZ. Procedures like laser bar welding give an exceptionally focused, restricted measure of warmth, bringing about a little HAZ. Bend welding falls between these two boundaries, with the individual procedures changing to some degree in warmth input. To ascertain the warmth contribution for curve welding methodology, the accompanying equation can be utilized:

$$Q = \left(\frac{V \times I \times 60}{S \times 1000}\right) \times \textit{Efficiency}$$

where Q = heat input (kJ/mm), V = voltage (V), I = current (A), and S = welding speed (mm/min).

The potency relies on the attachment method used, with secure metal arc attachment having a worth of zero.75, gas metal arc attachment and submerged arc attachment, 0.9, and gas wolfram arc attachment, 0.8.

The quality of a weld is additionally enthusiastic about the mix of materials used for the bottom material and therefore the filler material. Not all metals square measure appropriate for attachment, and not all filler metals work well with acceptable base materials.

#### Materials

1- Steels The weld capacity of steels is correspondingly relative to a property refered to because of the solidify capacity of the steel, that estimates the possibility of framing flesh eater electronic PC all through securing or warmth treatment. The solidify capacity of steel relies upon its concoction structure, with bigger amounts of carbon and totally unique alloying parts prompting an aton of durable solidify capacity thus a lower weld capacity. so on have the option to pick combinations made of the numerous unmistakable materials, a live referred to because of the equal carbon substance is utilized to coordinate the relative weld abilities of changed composites by examination their properties to plain steel. The outcome on weld capacity of parts like range 24 and V, while not as pleasant as carbon, is more crucial than that of copper and nickel, as Partner in Nursing precedent. because of the identical carbon substance rises, the weld capacity of the compound declines. The weakness to misuse plain carbon and lowamalgam steels is their lower quality—there might be an exchange off between material quality and weld capacity. High quality, lowcombination steels were grown impressively for securing applications all through the nineteen Seventies, and these commonly simple to weld materials have reasonable quality, making them perfect for a few affixing applications.

Hardened steels as a consequence of their high range 24 substance, will in general act generally with connectedness weld capacity than totally various steels. goals evaluations of clean steels will in general be the premier welds in partner degree passing position, anyway they're impressively in risk of contortion inferable from their high consistent of warm broadening. Some amalgams of this caring square measure obligated

to breaking and decreased consumption obstruction similarly. Hot breaking is plausible if the amount of essential goals at interims the weld isn't controlled—to mitigate the issue, Partner in Nursing conduit is utilized that stores a weld metal containing a tiny low amount of essential goals. varying kinds of perfect steels, as ferritic and martensitic clean steels, aren't as just welded, and can commonly be preheated and welded with extraordinary cathodes.

Aluminums: aluminum welding capability variesextensively; it depends on the material chemicals utilized. This material is in a risk of the ability to crack when getting hot. And to avoid that, welders work carefully and increases the welding speed and lowering the heat input, through pre-heating the welding zone to battle this issue. Meanwhile, this procedure may change the properties of the welding surface material, and ones the base material restrained, it should not be used. the appearance of the joint may change also. Therefore, the use of a good alloy filler will be beneficial to lower the risk of cracking while welding. Andbefore the welding procedure, its necessary the clean the alloys and remove all oxidizations, fluids, oils, smudges and particles from the surface for a proper welding scenario.

### **REFERENCES:**

- [1]. Wikipedia contributors. Welding. In Wikipedia, The Free Encyclopedia. (Accessed 13 July2019) from <a href="https://en.wikipedia.org/w/index.php?title=Welding&oldid=905401666">https://en.wikipedia.org/w/index.php?title=Welding&oldid=905401666</a>
- [2]. Segui, William T. Steel Design, 4<sup>th</sup> edition, Thomson. ISBN 0495244716, 2006.
- [3]. ASM International. Trends in Welding Research. Materials Park, Ohio: ASMInternational. ISBN 0-87170-780-2, 2003
- [4]. Blunt, Jane; Nigel C. Balchin. Health and Safety in Welding and AlliedProcesses. Cambridge: Woodhead. ISBN 1-85573-538-5, 2002.
- [5]. Cary, Howard B; Scott C. Helzer. Modern Welding Technology. Upper Saddle River, New Jersey: Pearson Education. ISBN 0-13-113029-3, 2005.
- [6]. Kalpakjian, Serope; Steven R. Schmid. Manufacturing Engineering and Technology. Prentice Hall. ISBN 0-201-36131-0, 2001.
- [7]. Weman, Klas. Welding processes handbook. New York, NY: CRC Press LLC. ISBN 0-8493-1773-8, 2003.
- [8]. Langrand, B., Deletombe, E., Markiewicz, E., &Drazetic, P. (2001). Riveted joint

- modeling for numerical analysis of airframe crashworthiness. Finite Elements in Analysis and Design, 38(1), 21-44, 2001.
- [9]. DuPont, J. N., & Marder, A. R. Thermal efficiency of arc welding processes. Welding Journal-Including Welding Research Supplement, 74(12), 406s, 1995.
- [10]. Jeffus, Larry. Welding: Principles and Applications. Cengage Learning; 7 edition May 12, 2011.
- [11]. Peterson, Chris. Welding Complete: Techniques, Project Plans & Instructions. Cool Springs Press. August 1, 2009
- [12]. Christena, Stephen. Learn to Weld: Beginning MIG Welding and Metal Fabrication Basics. October 10, 2014
- [13]. Uttrachi, Gerald. Weld Like a Pro: Beginning to Advanced Techniques. June 1, 2015

Ahmad Hussain Albloushi "Welding Techniques" International Journal of Engineering Research and Applications (IJERA), vol. 9, no. 12, 2019, pp 33-38